

Aerodrome Safety Standards Department
Sinamangal, Kathmandu
Exemption Granted to Biratnagar Airport



S.No.	Audit Finding No.	AGA Audit Finding of TIA	Exemption granted upto	Remarks
1	08	Operation of Biratnagar Airport with inadequate separation between runway and parallel taxiway.	14 March 2027	10 years
2	82	The width of runway strip at runway 27 is not as per CAR – 14, Part 1(required 150 mt. either side , available NE 106 mt. , SE 94 mt., SW after 75 mt. at runway 09)	14 March 2027	10 years

A handwritten signature in black ink, appearing to be "R. A. P. S.", is located below the table.