

CIVIL AVIAITON AUTHORITY OF NEPAL
AERODROME SAFETY STANDARDS DEPARTMENT
SINAMANGAL, KATHMANDU

EXEMPTION RECORDS

Name of Aerodrome	Exemption	Exemption granted up to
Tribhuvan International Airport (VNKT)	1. The width of runway strip on each side of center line of the runway does not comply with requirements set forth in Civil Aviation Requirement (CAR) -14 Part 1.	09 June 2027
	2. The minimum separation distance between parallel taxiway center line and runway center line does not meet the standards of Civil Aviation Requirement (CAR) - 14, part 1.	09 June 2027
Biratnagar Airport (VNVT)	1. Operation of Biratnagar airport with inadequate separation between runway and parallel taxiway.	14 March 2027
	2. The width of runway strip is not as per CAR – 14, Part-I.	14 March 2027
Nepalgunj Airport (VNNG)	The width of the Runway strip does not comply with the standard as per Civil Aviation Requirement (CAR) – 14, part I	17 June 2026