

**Aerodrome Safety Standards Department**

**Sinamangal, Kathmandu**

**Exemption Granted Record**

<b>Name of Aerodrome</b>	<b>Exemption</b>	<b>Exemption granted up to</b>
Tribhuvan International Airport (VNKT)	1. The extent of runway strip beyond runway 20 end and its width does not comply to the requirements set forth in Civil Aviation Requirement (CAR) – 14, part 1.	02 May 2024
	2. The minimum separation distance between parallel taxiway center line and runway centre line does not meet the standards of Civil Aviation Requirement (CAR) - 14, part 1.	02 May 2024