

# DOTI AIRPORT



## **Brief Description**

Doti Airport is situated at Dipayal Municipality of Doti District, Sudur-Paschim Province. The airport is now not in operation.

## **General Information**

Name	DOTI
Location Indicator	VNDT
IATA Code	SIH
Aerodrome Reference Code	1B
Aerodrome Reference Point	291547 N/0805610 E
Province/District	Sudur-Paschim / Doti
Elevation	577 m./1893 ft.

Contact	AFS: VNDTYDYX	
Operation Hours	Nov 1 <sup>st</sup> to Jan 30 <sup>th</sup> (Kartik 16 <sup>th</sup> to Magh 15 <sup>th</sup> )	1000LT-1600LT
	Feb 1 <sup>st</sup> to Oct 30 <sup>th</sup> (Magh 16 <sup>th</sup> to Kartik 15 <sup>th</sup> )	1000LT-1700LT
Status	Not in Operation	
Year of Start of Operation	24 September, 1973	
Serviceability	All Weather	
Land	Approx. 53244.47 m <sup>2</sup>	
Re-fueling Facility	Not Available	
Service	AFIS	
Type of Traffic Permitted	Visual Flight Rules (VFR)	
Type of Aircraft	DHC6, Y12	
Schedule Operating Airlines	None	
Schedule Connectivity	None	
RFF	Not Available	

### Infrastructure Condition

#### Airside

Runway	Type of Surface	Bituminous Paved (Asphalt Concrete)
	Runway Dimension	490 m x 20 m
	Runway Designation	14/32
Parking Capacity	Two DHC6 Types	
Size of Apron	1800 sq.m.	
Apron Type	Asphalt Concrete / Concrete	

#### Passenger Facilities

Hotels	Yes (city area)
Restaurants	Yes
Transportations	Taxi, Van
Banks/ATMs	No
Internet Facility	No
Cable TV	No
Baggage Trolley	No

## Airport Facilities

<b>Console</b>	One Man Position Tower Console with Associated Equipment and Accessories	
<b>Communication, Navigation &amp; Surveillance Systems</b>		
	Communication	HF SSB, VHF
	Navigation	No
<b>Security and Facilitations</b>		
	X-Ray	No
	Metal Detector	No
	CCTV Surveillance System	No
	UHF Band Communication System	No
	FIDS	No
<b>Meteorological Services</b>		No
<b>Electro-Mechanical Facilities</b>		
	Supply Conditions	Single Phase Supply
	Approach Light	No
	PAPI/APAPI Light	No
	Stand -by-supply	No
	Air Conditioner	No

Profile Edited on: 12th Feb, 2020